



Rostra Precision Controls, 2519 Dana Dr., Laurinburg, NC 28352
1-800-782-3379 www.rostratransmission.com

NOTE: THE SHIM INCLUDED WITH THIS PRODUCT MAY NOT BE REQUIRED FOR ALL APPLICATIONS.

To determine if the included shim is necessary, it is suggested that a feeler gauge is used to determine if a .060 gap is present between the solenoid bracket and the mounting point on the valve body prior to tightening the retainer bolt.



Check for gap



Insert shim if required




Tighten bolt
FORM #5234, Rev. RTP, 01-07-10




Rostra Precision Controls, 2519 Dana Dr., Laurinburg, NC 28352
1-800-782-3379 www.rostratransmission.com

NOTE: THE SHIM INCLUDED WITH THIS PRODUCT MAY NOT BE REQUIRED FOR ALL APPLICATIONS.


To determine if the included shim is necessary, it is suggested that a feeler gauge is used to determine if a .060 gap is present between the solenoid bracket and the mounting point on the valve body prior to tightening the retainer bolt.



Check for gap



Insert shim if required



Tighten bolt
FORM #5234, Rev. RTP, 01-07-10